Inspection Report

Name of Work: Improvements of drain in 2nd main,1st A main,3rd main road at Defence colony in Ward No 14

B.R.No: 453/31.07.2014

Estimate Cost: 20.00 Lakhs

Bill Amount:

Date of Inspection 05-03-2016.

Observation and Conclusion:

The above work was shown to me by the Concerned ward Engineer.

The above said work is inspected by me along with the Concerned ward Engineer

The work done is Satisfactory

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Name of Work: Improvements of drain in 2nd main,1st A main,3rd main road at Defence colony in Ward No 14

BR No. 453/14-15, Date.31.07.2014

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements of drain in 2nd main,1st A main,3rd main road at Defence colony in Ward No 14

BR No. 453/14-15, Date.31.07.2014

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಿಬಿಎಂಪಿ, ಬಿಬಿಎಂಪಿ

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: Improvements of drain in 2nd main,1st A main,3rd main road at Defence colony in Ward No 14

BR No. 453/14-15, Date.31.07.2014



location of works spot

Verified

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT